

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5






FIG. 6




ALT. EMBODIMENT #2

FIG. 7




ALTERNATIVE EMBODIMENT #2  
 FIG. 8




ALT. EMB. #3  
FIG. 9





Lower Coil Form / Shield combination, made by stacking thin, ferrous laminations.



Exploded view showing use of sintered or molded end caps.

ALT. EMB. - LAMINATED BOBBIN/SHIELD  
FIG. 10